

## FE CONNECTION/TERMINATION KITS



FECABUC Contents

### FECABKC: Lead/End Termination Kit

5 - Lead pouches  
5 - End pouches  
10 - Shrink tubes  
Enough to complete five lead terminations and five end terminations.

### FECABUC: Universal Connection/Termination Kit

3 - Lead pouches  
2 - End pouches  
6 - Shrink tubes  
1 - 3 oz (89 ml) tube RTV sealant  
1 - Caution label  
2 - Ring terminals  
2 - Splice connectors 12-10  
3 - Wire nuts  
1 - NPT Pipe standoff  
2 - Pipe straps  
Enough to complete one power input connection or one power input splice, three lead terminations and two end terminations.

*NOTE: Requires double hub junction box.*

### FECABLP: Lead Termination Kit

1 - Lead pouch  
1 - Shrink tube  
Enough to complete one lead termination.

### FECABSK: Splice Kit

3 - Lead pouches  
1 - End pouch  
4 - Shrink tubes  
1 - 3 oz (89 ml) Tube RTV sealant  
1 - Caution label  
3 - Ring terminals  
3 - Splice connectors 12-10  
Enough to complete one in-line splice or one tee splice, three lead terminations and one end termination.

*NOTE: Requires single hub junction box, pipe standoff, two pipe straps.*

### FECABEP: End Termination Kit

1 - End pouch  
1 - Shrink tube  
Enough to complete one end termination.

## KE/KM/KK CONNECTION/TERMINATION KITS



KCABUC Contents

### KCABKC: Lead/End Termination Kit

5 - Lead pouches  
5 - End pouches  
1 - 3 oz (89 ml) Tube RTV sealant  
Enough to complete five lead terminations and five end terminations.

### KCABUC: Universal Connection/Termination Kit

2 - Lead pouches  
2 - End pouches  
1 - 3 oz (89 ml) Tube RTV sealant  
1 - Caution label  
2 - Ring terminals  
2 - Splice connectors 12-10  
2 - Wire nuts  
1 - NPT pipe standoff  
2 - Pipe straps  
Enough to complete one power input connection or one power input splice, two lead terminations and two end terminations.

*NOTE: Requires double-hub junction box.*

### KCABLP: Lead Termination Kit

1 - Lead pouch  
Enough to complete one lead termination.

*NOTE: Requires RTV silicone*

### KCABSK: Splice Kit

3 - Lead Pouches  
3 - End pouches  
1 - 3 oz (89 ml) Tube RTV sealant  
1 - Caution label  
3 - Ring terminals  
3 - Splice connectors 12-10  
Enough to complete one in-line splice or one tee splice, three lead terminations and three end terminations.

*NOTE: Requires single hub junction box, pipe standoff, two pipe straps.*

### KCABEP: End Termination Kit

1 - End pouch  
Enough to complete one end termination.

*NOTE: Requires RTV silicone.*